

Name: _____

VISTAMETALS

Address: _____

13425 Whittram

SIC.# _____

City, Zip: _____

FONTANA

SITE DRIVE-BY

SFUND RECORDS CTR
2389877

1. Status a. Active ☒ Inactive ☐ b. Different Company _____
2. Setting a. Urban ☐ Suburban ☒ Rural ☐ b. Residential ☐ Commercial ☐ Industrial ☒ Other _____ c. Near: RR tracks ☒ Drainage ☐ Freeway ☐ Other _____
3. Waste a. Group 1 ☐ Group 2 ☐ Group 3 ☐ b. Liquid ☐ Sludge ☐ Solid ☐ Other _____ c. Undetermined ☒ None Visible ☐
4. Waste Containment a. Pond ☐ Sump ☐ Pit ☐ b. Drum/Brl ☐ Pail/Can ☐ Trash can ☐ Dumpster ☐ Box/Pallet ☐ Bag/Sack ☐ Vehicle ☐ c. To: Ground ☐ Paving ☐ Drain ☐ Other _____
- d. Piled ☒ ?
Scattered ☐
5. Miscellaneous a. Odors NONE b. Vegetation NONE c. Topography flat d. Site Observability _____

6. Map & Comments

A graphic site description. In addition to above, draw, describe and comment on the following: Buildings, Paving, Storage (raw material and products) Security, Vacant Areas, and Housekeeping. Also identify streets, landmarks, directions, etc.

large facility - walled & fenced - difficult to observe.
Tractor (loader) was in process of moving gray piles of material stored on paved lot to another area. (not covered)
- also have black piles of material in adjacent lot (not covered) - uncertain if paved.

7. Evaluation

- a. No Problem ☐ c. Possible Abandoned Site ☐

b. SAP Follow-up ☒: _____d. Referral to ☐ _____

Date: _____

6/13/84

Name: _____

Mary Osborne